



Die Uhr wurde zu uns in den Service gegeben, weil sie nicht genau geht. Dieses Verhalten wurde überprüft und es wurde keine Fehlfunktion festgestellt.

Es kann bei dieser Art Uhren vorkommen, dass die Spiralfeder überschlägt - dies geschieht unbeabsichtigt durch einen Stoß oder eine unbedachte Bewegung des Trägers.

Dieser Fehler kann von jedem Uhrmacher auf der ganzen Welt in kürzester Zeit behoben werden. Es wird deutlich günstiger, diesen 'Fehler' von einem Uhrmacher bei dir zuhause korrigieren zu lassen, anstatt die Uhr hierher nach Deutschland zu senden.

The clock was given to us in the service because it does not go exactly. This behaviour was verified and it was found not a malfunction.

It can occur during this kinds watches that the spiral spring rolls over - this is done unintentionally by a shock or a careless movement of the wearer.

This error can be resolved by any watchmaker throughout the world in no time. It will be much cheaper to have correct this 'error' by a watchmaker in your city, rather than sending the clock here to Germany.

*With special greets from your
Watchmaker Marty*